

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer)

- | | |
|--|---|
| 1. Name of Officer | : Sabitha - V. S |
| 2. Name of School | : Eran Academy for Sports and Excellence (EASE), Prabhapuram |
| 3. Location / with name of Education Dist. / Sub. Dist. | : Ottappalam Edu Dist / Pattambi Sub Dist |
| 4. Classification of building and size | : |
| 5. Period to which the certificate issued | : 2024-25 |
| 6. Nature of defects if any | : G.F, F.F, S.F; 1) 6.20x6.20x3.70 (38 class rooms) |
| a) Foundation and Basement | : G.F, F.F, S.F; 6.20x9.30x3.70 (3 Rooms) |
| b) Super structure | : G.F, F.F, S.F; 6.20x9.40x3.70 (3 Staff rooms) |
| c) Doors and Windows | : G.F, F.F; 6.00x6.00x3.70 (2 office rooms) |
| d) Wood work wroughts pull up | : Nil |
| e) Roof | : G.F; 6.40x6.00x3.70 (1 office room) |
| f) Flooring | : G.F, F.F, S.F; 9.40x5.90x3.70 (3 conference room) |
| g) Miscellaneous (cracks etc.) | : F.F, S.F; 9.60x6.00x3.70 (2 class rooms) |
| 7. Any major defects noticed which will render the building unsafe in any manner | : Nil |
| 8. Whether maintenance works have been done properly. | : Yes |
| 9. Whether the structure is sound on for conducting classes | : Yes, sound under normal wind weather and climatic condition |

- Note :-
- The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
 - Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 25/4/2024

and founded to be Fit/Unfit

to conduct classes for the period 2024-2025
for the reason noted above.

Place: Koppam

Date: 31/05/2024



Signature: [Handwritten Signature]
31/05/2024

Designation: **ASSISTANT ENGINEER**
LID & EW SECTION
KOPPAM GRAMA PANCHAYATH